MISSION COORDINATOR CHECK LIST

	25X1A FROM: START TO: H-24 (//00)
TIME (NLT) RESP	ACTION COMPLETED
25X1A ASAP DCOC [ASAP DCOC	Complete & distrubute mission alert 0/0 for notification Acknowledge Receipt of 0650 for Convert H -hour time to local and 07/5 for record in check list. Complete pilots activity schedule 0705 for formula for the complete pilots activity schedule 0705 for formula for
25X1A ASAP DCOC 25X1A 25X1A	(5) (1-DCO, 1-M/C, 1-Flt Surg, 1-CO, 1-DCOL) Notify & alet the C-130 (21 TCS) (830 A) Advise that we have an airlift requirement to 2. In place time here to pick up TAKE is L+2.00.
25X1A	check with DCOM to see if Msgs 3/003336 prior to H-24.
	Check with DCOM FOR the check list <u>A 760</u> to be used. (a) Custom or canned route.
	(b) Custom route w/option (Delete non-applicable items from M/C Checklist i.e. DCOM (A) DODM (B) Delivers tanker schedule with all/208 C/S - & timing.

Page 1

revised 16 Sept 67.



A SEE

	,	FROM: H -24:00(9/1/	'00 L)
		то: н -18:00(/	700 L)
TIME NLT	RESP	25X1A ACTION	TIME
H -24:00(6/100 I	DCOM(B) Received (Via 1004)	- 5700 Ph
H -23:30(//30 I	DCOC/	M/C attend Commander's initial briefing. Receive Ops personnel inputs for recovery team. Give to DCS. Prepare access lists for CP and Flt Following Room.	25X1A
н -23:00(<u>/260</u> г) SEC	Hangars secured, access lists posted.	1200
н -22:00(<u>/300</u> 1) COMMO	Recd Prepare Flimsy	0700
H -21:00(<u>/400</u> I) Flt Surg	Results of pilot physicals	1400
H -21:00(<u>/400</u> L)	DCOC	Send 25X1A	1004
H -20:30(<u>/430</u> I) COMMO	Notify DCM of Freq Channelization and translator code.	1515 (forge
н -19:00(<u>/600</u> г	DCM	Complete TEB and Refuel (Item 8) #1 * (Item 3) #2	1530
н -19:00(<u>/600</u> г) SEC	Advise M/C of Seat Kit No. Prm_AC I	(it 105
H -19:00(<u>/600</u> L) DCOM	Tape Recorders ready in briefing Rr	1600

25X1A

Complete Commo flimsy, cys to: M/C-3, (2 Pilots + 1 CP) and DCOMF-2

H'-19:00(<u>/660</u>L)

* DCM REGENERATION

COMMO

TO: H-12:00 (2300 L)

FROM: H-18:00 (1700 L)

	1			<u> </u>
	TIME (NLT)	RESP	ACTION	TIME
	H-18:00(<u>/700</u> L)	DCOMI	Start Intelligence Briefing	0706 Ma
	H-17:00(/800 L)	DCO	Supervise Plt's Initial Briefing	1800
	H-16:00(/960L)	DCM	Complete INS pre-flt (item 12) #1	1430
05)			25X1D _{#2}	1700
25X1A	H-15:00(2000 L)	DCOM(A)	Receive (Via 1004)	0700 Ha
25X1A	H-15:00(<u>2000</u> L)	DCM	Deliver with Checkout Info.	NIR
25X1A	H-15:00(2000 L)	COMMO	Deliver to M/C if all Info available.	14.45
	H-13:00(2200 L)	DCM	Complete (Item 13) #1	1500
		·	25X1D #2	1730
	H-13:00(2200 L)	DCOM(A)	INS Load Sheet. Deliver to INS	09/11/0Ca
	H-13:00(2200 L)	Flt Surg	Start Crew Rest 25X1A	09/22001
0EV4%	H-12:30(2236 L)	DCOM	Notify M/C of receipt of Pkg Data) (Via 1004)	0/0900000
25X1A	H-12:00(<u>2,360</u> L)	DCOC	Send Support Msg to 313th	1239
¥.	H-12:00(<u>2300</u> L)	DCOM(A)	Receive Wea update flt plan (Via 1004)	10/0445 4
4 :			en e	•

Page 3

Revised 11 September 1967





25X1A

FROM: H-12:00 (2300 L)

TO: H- 2:00 (4/0/00 L)

			1	7	
	TI	ME(NLT)	RESP	ACTION	TIME
	H-:	11:30(2330 L)	DCOM	Package program to Pkg personnel	09/8915 Ota
make the way of the state of th	H-	9:00(<u>0200</u> L)	DCOW	M/C item (G) Wx effect of ability to launch.	09/2/AC
	H-	9:00(<u>0200</u> L)	DCOC	Send to Hqs	092100
	Н-	8:30(<u>0230</u> L)	DCM	Complete Pkg Load (Item 15) #1	80/0055L.
7		•		#2	10/0120 L.
	H	6:00(<u>0500</u> L)	DCOC	DCOM(B) advise 313th of Option	
	-H-	5:30(L)	DCOM(B)	Previde load sheet to INS	
	-H-	5:00(L)	DCOM(B)	Receive Wx update flt plan	
	H-	4:30(<u>0630</u> L)	DCOM(A)	Film strip complete	05456
	H -	4:00(<u>6700</u> L)	AFCS	Report Equip status to DCOC	0650
	H-	3:45(<u>07/5</u> L)	CMDR DCO F/Surg	Final decision on primary & spare pilot, notify DCOL	0715
		3:45(0 <u>7/5</u> L)	DCO	Current Airfield Status	0715
25X1A	Ή-	3:30) <u>4730</u> L)	DCM	Start INS (Item 21) #1	0725
		£	•	*(Item 14) #2	0730
	Н-	3:30(<u>0730</u> L)	DCO	Final Briefing	0730
	Н-	2:30(<u>0830</u> L)	DCOC	Send confirmation of coord.	04002
*					

DCM REGENERATION

25X1A

Page 4

Revised 15 September 1967



	1	•		:
			FROM: H -2:00 (09	Ø Ø L)
			TO: L HOUR (//	00 L)
	TIME (NLT)	RESP	ACTION	TIME
	H -2:30(C 930 L)	DCOC N		0905
	H -2:00(0 900 L)	(1	CONTRACERS RE Packet turned in to DCOL	0900
	H -1:35(0925 L)		etdown plates to pilots	
	H -1:30(1)		Film strip complete #1	
	H = 1 - 3 - 4 - 1 / 1		#2_	
	H1:25(_ 0935 _L)	F/Surg F	Pre-suiting physical	0935
	H -1:00(<u>/000</u> L)			1000
-	H -1:00(<u>////</u> L)	DOOM 1	#2	1000
		DCOL 1	Pilot to aircraft	1100
	H -0:50(/0/0 L)		Go-No-Go decision	1000
	H -1:00(/000 L)		Activate HF (CONTROLLER)	1000_
	H-1:00(/000 L)		Check latest NOTAMS	1000
	H -1:00(/g f0 L)		Assure Chopper alerted	1000
	H -1:00(/600 L)		Pilot hooked up in acft	1015
	H -: 45(/0/3 L)			1030
	H -: 30(<u>/.030</u> L)		Start engine	1045
25X1A	H -: 15(/0 45 L)	DCOC	Cmdr's emerg C.L., Dash-1, CYG Ck list, in place	
25X1A	H -:00(//00 L)	DCOC	Send	1100
20/1/	H Hour(//00 L)	DCOC	Send T/O.Msg to 313th	1100
	H +1:15(1715 L)	DCO	Release spare (primary)	1205
	:30 prior to ldg	DCOC	Alert chopper (controller)	1415
	:30 prior to ldg	DCOC	Notify Transit Alert (controller)	145
25X1A	:30 prior to ldg	M/C	Prepare for DTFC or DCO	1415
, i.			(clip bd) (primary)	1450
25X1A	ASAP after ldg	DCOC	Send (Msn ldg report)	1450
	ASAP after ldg	DCOC ******	Send 313th CNX (ATA) msg	
<u> </u>	Page 5 Approved For	r Release 2	002/06/10 : CIA-RDP69B00041Rติชารีอิซิติชื่อชื่อใช้	Aug 1967

The second secon	ase 2002/06/10 : CIA-RDP

XER		XERO
70-0	English the State	-

			<u> </u>
r en	,		TO: END
TIME (NLT)	i	RESP	<u>ACTION</u> TIME
			SECONDARY LAUNCHED 25X1/
ASAP	,	DCOC	Send on Primary
ASAP		DCOC	Send abort Msg on Prim
H'+1:00(_L)	DCOC	Send on Secondary
H +1:00(_L)	DCOC	Send I/O on Secondary
L -:30(L)	DCOC	Notify Nelicopter (controller)
L -:30(L)	DCOe	Notify Trans Alert (controller)
L Hour(_ <u>_</u>	DCOC	Send 25X
L Hour	_L)	DCOC	Send Canx - Give ATA
. "		****	*************
ASAP after ldg	1	DCOC	Receive CYG Down time, then release
ASAP after ldg		DCOC	Release Helicopter (controller) 1450
ASAP after Ldg		DCOC	Release C-130 (21TCS) 1450
L +:30(_L)	AFCS	Shutdown 25X1A
L +1:30(_L)	DCOMI	Par "C" of to DCOM
L .+3:30(SEC	Sterilize aircraft
L Plus (-L')	DCOC DCOM	Release Acft to DCM Recording tape and film strip to Security.
L +5:00(_L)	DCO	Review Tanker Msn Report
L +5:00(_L)	DCOM	Tape of debrief to Security
L +5':00(_L)	соммо	to Security

25X1A

Approved For Release 2002/06/10 : CIA-RDP69B00041R0 1300010008-6 25X1A *BLACKSHIELD* TITLE INACTION REMARKS Msn Alert Wx Fcst Χ WX (Receive Daily) 25X1A Daily Airfield Status · X DCOC As of 0900L (Controll) Filed in Folder -24 Tanker Msn Alert X SAC -24 Mission Alert CMDR/DCO X DCM ASAP 25X1A Ackd Receipt \mathbf{x} DCOC Mission Plan -23 Wx Requirement Х WX/DCO -22 Opln Commo Data X COMMO/DCO **-**22 25X1D 25X1D X Tanker/Wx Scout -22 X Recall Word SAC/DCO Mission Alert -21 ĵ, Confirmation DCO 1400 Tanker Support -21 Confirmation SAC 1400 sn Plan Wx Fcst X WX 1400 Forward Base Wx -21 Forecast

X

WX

DCO

CHANNELS 25X1A

PAGE 1 Approved For Release 2002/06/10 : CIA-RDP69B00041R001300010008-67

Wx Scout Request

1400

-20



Approved For Release 2002/06/10 : CIA-RDP69800041R0 1300010008-6



25X1A 2	5X1A					*BLACKSHIELD*
V	TITLE	DUE LCL Z	IN	רטטד	ACTION	REMARKS
NR	HF Freg to TTFC	-20 i 5 00		Х	соммо	As Req of Typhoon Depl
	MISSION PLAN#1	-18 17æ	х		DCOMP	
	Current Intel	-18 17au	¥		INTEL	
	Msn Pln Wx Fcst	-17:30 (730	x		wx	
	Wx Support Confirmation	-17:30 (730	х		DCOC	
	Weather Scout Call Sign Confirmation	-17:00 /800		(X)	DCO	Wx Scout Call Signs to
	Forward Base Wx Forecast	-17:15 /245	х		wx	25X1A
	Opln Capability	-16:00 <i>190</i> 0		X	DCM	As of 1700 Local Daily
	Supt Acft Statu	-15:00 2000	T	X	DCM	As of 1700 Local Daily
	Mission Pln#2	-15:00 2 <i>00</i> 0	x		DCOMP	Probably 1004
	Mission Plan#3 -	-15:00 Zew	X		DCOMP	Probably 1004
1/2		-15:00 Tevo	-	х	DCM	REQUIRED ONLY WHEN SO INDICATED ON BOTTOM OF
1A	GO-NO-GO Wx Requirements	NLT 1330Z	- x		Wx	25X1A 25X1D
	Approved For Releas	The supplier of the last of th	CIA-RI	DP69E	300041R00 SAC/WX	1300010008-6

	•	Approved For Relea	se 20 0	2/06/10 : C	IA-RDI	P69E	000 4 1R0 0 130	00010008-6
udax							XERO	CODA
	25X	1A 25X1A 25X	(1A					*BLACKSHIELD*
V		TITLE	LCI	DUE Z	IN	נטס	ACTION	REMARKS
7		Tanker Msn Plan	22	13:00	х		SAC	Probably More Than 1 Msg
		Camera Program ing Data	22	·12:30	х		DCOMP	Probably 1004 25X1A
25X1A		Support Reques	^t 2 3	12:00 UD		X	DCO	CHANNELS Add Crew Number
25X1D			0/0	10:00		x	соммо	25X1A
		Non-Opnl Sortie	15.3	AILY		(x)	DCOC (CONTROLI	File in Folder Submitted Appox 1530L Daily For Next Days Non-Ops Mss
		Sp Fuæl Test	010	10:00		х	DCM(POL)	
		Forward Base Wx Forecast	ora	-9:00		х	WX	-
		Tanker Pre- Sortie Report .	1.	-9:00		χ	SAC	Probably More Than 1 Msg
		GO-NO-GO WX . Forecast	-	-9:00	х		wx	
		Pre-Sortie Report	J 70	9:00		(x)	DCO	
		Haz Wx Advisory		7:00		х	WX	If Adverse Conditions
		Haz Wx Advisory		7:00	х		WX	If Adverse Conditions
		Tanker Msn Support Execut- ion	050	6:00 V	х		SAC	
		Approved For Relea	se 20 <u>0</u> ⊋ 30		A-RD		00041R0013 DC <i>om</i>	00010008-6 25X1D

XEBO.		COBY				XERO	XERO
	. 25X	1A					**************************************
	V	TITLE	DUE ICL Z	IN	OUT	ACTION	*BLACKSHIELD* REMARKS
	NR	Final Option Selection	-6 0500 —	X		DCOM	
	/	Msn Alert Wx Fcst	-5 10600	x		wx	(Receive Daily)
		Emerg Seat Pack	-5 0600		X	SECURITY	
		Forward Base Wx Forecast	-3 USOU		X	WX_	
25X1A _		Met Watch Obs	-3 0800		X	WX_	
25X1	A		-3 0800	x		DCO	*
		GO-NO-GO Wx Forecast	-3 0 800	x		WX	
	1	Spl Fuel Test	-2:30 0830		Х	DCM(POL)	
		313 AD Coord Confirmation	-2:30 OF 3 0		(X)) _{DCO}	Submit to Hqs
	NR	Wx Scout Rpts	-2 0900	x		WX i	Will be Received Continuous Until AR Areas Secured
		Airfield Status	Daily			OCOC (Controll)	25X1A As of 0900 Local Filed in Folder
		Tanker T/O Rpt	As Req		Х	SAC _	Continous Until all Tankers
		GO-NO-GO Mags	-1 10th	X	·	DCO	
		Primary Take-off	-0		X	DCO	Add Crew Number

		Approved Fo	Release	2002/00	6/10 :	CIA-RDI	26 93 00
XEBO XEBO	and the second second	Approved Fo	COD XEBO				2344

	XEBO		02/06/10 : CIA-RDP6 B00641R 1300010008-6								
25X1A			.,		79 29	ALL VACULATION					
V	TITLE	DUE LOL Z	IN	OUT	ACTION	*BLACKSHIELD* REMARKS					
	Msn Post Landing	L Plus 2	C Colonia Colonia	X	DCO/CMDR						
	Tanker Landing	As Req		х	SAC	Continuous Until all Tankers Have Landed					
	Camera Config	L Plus 3		х	DCM	a Control of the Cont					
	Mission Report	L Plus 3		Х	DCO/DCOM	25X1A INFO: "EYES ONLY					
*=,	Spl Fuel Test	ASAP		х	DCM(POL)						
	Opnl Sortie Rpt	.'ASAP		х	DCO	25X1A Same as Nonop					
	INS Tape	ASAP		x	DCOMP	Via 1004 w/message back					
	Take Progress	ASAP		х	SECURITY						
	Final Field Eval Of INS Data	L Plus 10		X	DCM						
	Flash Process	ASAP	х		DCOMP						
	Film Evaluation	ASAP	х		DCOMP						
	INS Tape Eval	ASAP	Х		DCOMP	41					
× 7	INS Film Correle.	L Plus 7 Days	х		DCOMP						
D [TAKE PROGRESS ROT	ASAP		X.	SECURITY						

		Approved For Release					T		XERO	25X1A		
	IMMEDIATE	1								GENE	RAL MSG	FORMAT
25X1A	FROM: DET TO: AFSSO	4 313ADIV 313ADIV								N. Juffe V. Ader versee ville oldere		
20/1/	TOP SECRET	BLACKSHIELD		CHAI	4NFIL	d 	•	. i		707 - T- 204		
25X1A [1.	(Msg	#)		1					Addit Additional programmes Additional programmes		
							å			and the same of th		
			. 1							! ! !		
									1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			

(RELEASER & DTG)